ASSEMBLY INSTRUCTIONS FOR

1485X ADJUSTABLE FITTING AND STRAIGHT SECTION

REV. C


ASSEMBLY INSTRUCTIONS

LOOSEN NUTSAAND SCREWS HOLDING THE TOP PLATE ON THE COMPRESSION RING (PART 5). SLIP THE COMPRESSION RING OVER THE END OF THE ADJUSTABLE FITTING (PART 3). SLIP THE SOLID GASKET (PART 6) OVER THE END OF ADJUSTABLE

INSERT TIBLE ADJUSTABLE FITTING INTO THE MATING WIREWAY AND POSITION TO THE DESIRED LENGTH. MAX DISTANCE 7" (178mm).

SLIP BASE PLATE (PART 2) INTO MATING WIREWAY SO THAT THE TOP SEALING PLATE (PART 1) IS CENTERED OVER THE END FLANGE OF THE ADJUSTABLE FITTING. THE BASE PLATE IS SUPPORTED BY THE BASE PLATE SUPPORT ANGLE IN THE ADJUSTABLE FITTING.

FASTEN THE TOP PLATE DOWN SECURELY ON THE COMPRESSION RING AND TIGHTEN THE NUTS AND SCREWS SOLID GASKET TO THE FLANGE ON THE MATING WIREWAY USING 1/4 - 20 X.75 HEX HD. SCREWS AND 1/4 - 20 KEP NUTS







3/8, 7/16 Open End Wrench



