


Relay Rack & Cable Manager assembled



Mounted Back to Back
Top View

ASSEMBLY INSTRUCTIONS:

- A) Line up the back of the cable manager with the back of the relay rack, then lift the cable manager so it is flush with the top of the relay rack. (3 sets of holes should now line up)
- B) Using the hardware supplied, insert two bolts through the cable manager and relay rack at the top then fasten loosely using washer and nut.
- C) Insert the remaining hardware at 2 other points, (center and bottom), fasten loosely.
- D) Ensure that cable manager is sitting square then tighten all bolts.

* For use with RB-2PA relay rack series.

PARTS LIST		
ITEM No.	DESCRIPTION	QTY
1	CABLE MANAGER	1
2	SCREW 1/4-20 X 1/2 CARRIAGE	6
2	SCREW 1/4-20 X 1/2 ROUND HEAD *	6
3	NUT 1/4-20 KEP	6
4	WASHER FLAT 1/4	6

TOOL BOX



Phillips
Screw Driver



7/16 Socket
Driver



HAMMOND
MANUFACTURING™
ELECTRONICS GROUP

visit our website @ www.hammondmfg.com